Deficiency 23: (Cite 641 IAC Chapter 15 violation and manner in which the facility failed to comply)

Mechanical Room #12 No Knowledgeable person person in testing water/operating water treatment equipment available.

Corrective Action Plan: (this section to be completed by the facility to indicate how the deficiencies will be corrected)

Deficiency 24: (Cite 641 IAC Chapter 15 violation and manner in which the facility failed to comply)

Mechanical Room #13 Several pool/spa testing reagent bottles for the Taylor test kits are expired. Replace.

Corrective Action Plan: (this section to be completed by the facility to indicate how the deficiencies will be corrected)

Deficiency 25: (Cite 641 IAC Chapter 15 violation and manner in which the facility failed to comply)

Chemical Storage #1Bottles of liquid muriatic acid stored on top of a 5 gal bucket of powder sodium bicarb in small pool room storage closet.

Corrective Action Plan: (this section to be completed by the facility to indicate how the deficiencies will be corrected)

Deficiency 26: (Cite 641 IAC Chapter 15 violation and manner in which the facility failed to comply)

Chemical Storage #3 A chemical placard is not posted on the Pool Mech Room door. Blue barrel of sodium hypo stored in room.

Corrective Action Plan: (this section to be completed by the facility to indicate how the deficiencies will be corrected)

Deficiency 27: (Cite 641 IAC Chapter 15 violation and manner in which the facility failed to comply)

Corrective Action Plan: (this section to be completed by the facility to indicate how the deficiencies will be corrected)

Deficiency 28: (Cite 641 IAC Chapter 15 violation and manner in which the facility failed to comply)

Corrective Action Plan: (this section to be completed by the facility to indicate how the deficiencies will be corrected)